

4600 Highway 183 Alternate Hays, KS 67601 (785) 625-6346 Fax (785) 625-2795 www.rans.com

| Airworthiness Directive: | 134  |
|--------------------------|--|
| Date:                    | September 18, 2006   |
| Subject:                 | Tail Spring Breakage   |
| Compliance:              | Mandatory  |
| Models Affected:         | All Tail Wheel Models using Mounting Straps.<br>(S-6ES, S-6S, S-6LS, S-7, S-7S, S-7LS, S-16, S-17, S-18) |

The following steps should be taken to lessen the chance of tail spring breakage.

- 1. Suggested life limit of the tail spring is 500 hours.
- 2. Remove and inspect during every Annual Inspection for cracks and/or corrosion.
- 3. Modify Mounting Straps as per the drawings on the following pages. Pillow Block Straps may be modified by clamping in a vise and filing. A new contoured Gear Strap (KPTG0036) may be ordered from RANS Parts Department to replace the Pillow Block Straps, if you desire not to modify the part yourself.

Thank you for your attention to this matter. Hopefully, we have not inconvenienced you to any great degree.

Fly safe.









