

Airworthiness Directive: 120

Date: January 22, 2001

Subject: Elevator Yoke Exit

Compliance: Manditory

Models Effected: S-6S & S-6SXL Coyote II

NOTE: Applies to "curved" longeron tail cones ONLY.

Please use the enclosed information to verify that your elevator yoke exit is in the correct location.

Thank you for your attention to this matter. Hopefully we have not inconvenienced you to any great degree. Fly safe!

14X0170CV msw

7/27/00

