

RANS

4600 Highway 183 Alternate
Hays, KS 67601
(785) 625-6346
Fax (785) 625-2795

Assembly Alert: 168

Date: July 28, 2009

Subject: Incorrect hinge material (P/N's MS20257-3 and KPHS0080)

Compliance: Mandatory

Models Affected: S-19

It has come to our attention that a few S-19 kits may have been delivered with the wrong hinge material.

The **correct** hinge has "MS20257-3" stamped on the surface of the hinge every few inches and the hinge pin measures approx .090.

The **incorrect** hinge has no MS number stamped on the hinge and the hinge pin measures approx .125.

If your hinge material is **incorrect**, please return the material to RANS for replacement. **Do not fly on this hinge!**

Thank you for your attention to this matter. I hope that we have not inconvenienced you to any great degree. Fly safe!